

Received w/ signature July 16, 2011
R.F.

REQUEST FOR INSPECTION

To,
The Executive Secretary, The Inspection Panel,
1818 H Street, NW,
Washington, DC 20433, USA

Subject: Corruption and Fraud in the project I.D No. P073370, WB Loan/Credit No IN --
4750, M.P. Water Sector Restructuring Project. INDIA.

- (1) We are the applicants, citizen of India and Resident of M.P
- (a) Ram Sharan Gupta S/O Shri Ram Das Gupta, Retired Assistant Engineer, Age-62 years, R/O MIG 874, Darpan Colony, Gwalior, M.P - 474011,
Ph no - +91 7512341644, 9926648830
E-mail - rsgupta49@yahoo.com
- (b) Dinesh Singhal S/O Late Shri Megh Raj Singhal, Engineers and consultants,
Age - 51 years, R/O J - 47, Gandhi Nagar, Gwalior, M.P - 474002

- (2) We have suffered and harmed because of the World Bank's failures or omissions in the project I.D No. P073370, WB Loan/Credit No IN - 4750,
M.P. Water Sector Restructuring Project. INDIA.

**Enhancement of Water Quality of Swarna Rekha River, Gwalior,
M/S Uday Pratap Sharma, Rs. 3784 Lakhs (9.515 Million U.S. Dollars)**

- (3) Brief description of harm, corruption, fraud, failures and sufferings from this project:-
- (a) Illness;- Whole project creates mud and water slumps, which causes Dengue and Malaria. Bank is failed to control the dirtiness and slums in the Gwalior city.
- (b) Sewage system;- Main trunk lines are crushed and choked due to construction work and poor supervision. Small ponds of dirty sewage water formed in the river. From 2.50 Km to 5.00 Km main trunk lines are still choked, Raw sewage is flowing in the river.
- (c) Poverty;- It is increased. More than 1 lakh people are affected. They are wasting their money in medicines and treatment.
- (d) Quality of work;- It is not good, it is poor. Work of 15 months is not completed in 39 months. In so many places, drainages and seepages lines in the lining work are not given, which stopped free flow of sewage in the center of river. It is due to bad supervision. Work is not done as per design and specification.

- (4) List of Bank's operational policies, which are not followed properly as per operation Manual of World Bank.

- (a) World Bank local teams have inspected this project so many times. Reports of these teams were also given to the Project Director and Chief Secretary M.P. Govt. M.P. Govt. is failed to provide skilled supervision.

(b) Poverty Reduction (OP 1.00) :-

Project goal is not achieved. Only few officers, contractors became rich, due to high corruption. It is increased. More than 1 lakh people are affected. They are wasting their money in medicines and treatment. In all manners OP 1.00 is failed.

(c) Environmental assessment (OP 4.01) :-

Whole project creates mud and water slumps, which causes Dengue and Malaria. Bank is failed to control the dirtiness and slums in the Gwalior city. Main trunk lines are crushed and choked by the contractor, From 2.50 Km to 5.00 Km main trunk lines are still choked, So raw sewage is flowing in the river.

(d) Project Supervision (OP 13.05) :-

"Project Supervision covers monitoring, evaluative review, reporting and technical assistance." Accountability and responsibility have not taken by any officer. Here bank is failed. When work will complete? *Work is stopped from last 03 months.*

(e) B.P 13.05 – Project Supervision. Task team (TT) and team leader (TL) both are failed to supervise the project, technically and physically. that resulted poor quality of works, which creates so many problems, choking of sewage lines, etc.


(f) Mr. M.D. Naroliya was Chief Engineer from August 07, 2009 to January 31, 2011 (for 18 months). In this period he has not done proper supervision so this project is failed from so many angles.

(5) We have complained the matter to World Bank staff i.e. Country Director, New Delhi, Hon'ble Vice President, South Asia resign and other staff on September 16, 2010. We have also submitted about 500 photos and 200 E-mails in last one year. Country Director and his team, World Bank, New Delhi have visited this project on Feb 18, 2011, they have tired, but they are failed to solve the problems.


(6) We request the Inspection Panel recommend to the World Bank's Executive Directors that an investigation on these matters be carried out.

We request that the Inspection Panel should visit this project as soon as possible. So the problem of more than one lakh people may please be solved.

We will give full co-operation to inspection team at Gwalior.



(RAM SHARAN GUPTA)
MIG 874, Darpan Colony,
Gwalior, M.P – 474011,
+917512341644, 9926648830



(DINESH KUMAR SIGHAL)
J – 47, Gandhi Nagar
Gwalior, M.P. 474002

Date - *wednesday, July 06, 2011*

Note – Other details will be submitted by E-mail.